RECEIVED

HISTORIC PRESERVATION PROPERTY TAX EXEMPTION APPLICATION PART I--PRECONSTRUCTION APPLICATION | With the property of the proper

INSTRUCTIONS: Read the attached instructions carefully before completing this application. Your application cannot be evaluated unless it is complete and all required supporting materials are provided. In the event of any discrepancy between the application form and other supplementary material submitted with it (such as architectural plans, drawings and specifications), the application form shall take precedence. Type or print clearly in black ink. If additional space is needed, attach additional sheets.

A. GENERAL INFORMATION To be completed by all applicants 1, Property identification and location: Property Identification Number (from tax records): 070928 Attach legal description of property. Address of property: 152 East 4th Street City JACKSONVILLE, County: DUVAL Zip Code: 32206 ☐ Individually National Register Listed Locally designated historic property or landmark* In a National Register District In a locally designated district For applications submitted to the Division of Historical Resources, attach a copy of the local designation report for the property and the official correspondence notifying the property owner of designation. Name of historic district: Springfield For locally designated historic properties or landmarks, or properties located in locally designated historic districts, provide the following additional information: Name of local historic preservation agency/office: CITY OF JACKSONVILLE, PLANNING AND DEVELOPMENT DEPARTMENT Mailing Address: 128 EAST FORSYTH STREET City: JACKSONVILLE State: FLORIDA Zip Code: 32202 Telephone Number: (904) 630-1900 2. Type of request: Exemption under \$196.1997, F. S. (standard exemption) Exemption under \$196.1998, F.S. (exemption for properties occupied by non-profit organizations or government agencies and regularly open to the public) If applying under \$196.1998, F.S. complete Question 9 on page five. 3. Owner Information: Name of individual or organization owing the property: Hailing Zhong Mailing Address: PO Box 13314 City: Jacksonville, State: FL Zip Code: 32206 Daytime Telephone Number: (904) 210 1555

If the property is in multiple ownership, attach a list of all owners with their mailing addresses.

Name of additional owner at same mailing address:

Daytime Telephone Number: (____)_

4. Owner Attestation: I hereby attest that the information I have provided is, to the best of my knowledge, correct, and that I own the property described above or that I am legally the authority in charge of the property. Further, by submission of this Application, I agree to allow access to the property by representatives of the Division of Historical Resources or the Local Historic Preservation Office, where such office exists, and appropriate representatives of the local government from which the exemption is being requested, for the purpose of verification of information provided in this Application. I also understand that, if the requested exemption is granted, I will be required to enter into a Covenant with the local government granting the exemption in which I must agree to maintain the character of the property and the qualifying improvements for the term of the exemption.

Name: Hailing Zhong Signature:	Date:	3/4/2014
Complete the following if signing for an organization or multiple owners.		
Title: Organization:		

B. EVALUATION OF PROPERTY

To be completed only for properties in historic or archaeological districts:

4. Description of physical appearance:

The building is located within the National Historic District of Springfield. This two-story, metal-roofed, unpainted Queen-Ann style building, was constructed around 1902 and the adjacent rectanglular single story building was constructed in 1953. It's Queen Ann style tower has alternating bands of variouse patterned shingles although the spire has been removed.

On the interior of the first floor, the north west room has three windows open to the front porch and one window to the yard on the west side of the house. The fireplace was remodeled to accomdate a gas log but the ornametal mantle and decorative columns are still intact. The west middle room has a half turret attached to it's west side with curved windows. The fire place in this room has also been remodeled to accomdate gas log and is missing one of it's decorative columns. The west backroom has been partitially gutted and connected to the enclosed porch on the southwest corner of the house. The enclosed porch has modern windows. The kitchen on the southeast corner of the house has modern cabinets and a tiled floor. The wood kitchen door to the eastside of the house is not historic in age or style. The bathroom on the middle east of the house has modern tiles and appliances. The northeast corner coorespond to the interior of the tower and wood staircases leads to the second floor. Most of the first floor has wood floors.

The second floor interior has similar floor plan of the first floor except the walls of the hallway is angled at the end. The two bathrooms contain no historical feature and contain all modern tile and appliances except a claw foot bath tub. The shower in the bedroom at the southest corner of second floor has hexogonal windows that cannot be opened. The bathroom on the southwest corner of the second floor opens to the open porch with damaged railing.

Throughout the hosue there are several stained glass, or stained glass like, windows that can not be opened. The windows are protected from the outside with plexiglass.

Date of Construction:	approx. 1902	Date(s) of Alteration	(s): misc undated
Has building been mo	ved? 🔲 Yes	No If so, when?	

Statement of Significance:

Originally, numerous Queen Anne style building were built in Springfield around the turn of the century. As popular tastes changed after World War I, many of these turnets were removed or the buildings were demolished. Only few of these buildings remain in Springfield today. This building is typical in appearance for these turn of the century Queen Anne style buildings with turnets. The building was used continously as a residence. The modern additional building next to the main house was used as a barber shop in more recent times.

6. Photographs and Maps:

Attach photographs, site plans, floorplans and maps to application.

C. DESCRIPTION OF IMPROVEMENTS

To be completed by all applicants. Include site work, new construction, alterations, etc. Complete the blocks below.

FEATURE 1

Feature: Kitchen door (East side) Approximate date of feature: 1990

Describe existing feature and its condition:

Off the shelf wood door damaged by exposure to elements

Photograph Number: 4,5,6 Drawing Number: 1,3

Describe work and impact on existing feature:

The door will be replaced with a special ordered wood door matching in appearance the existing front door

FEATURE 2

Feature: Kitchen

Approximate date of feature: 1990

Describe existing feature and its condition:

Off the shelf wooden cabinets, partially completed and

damaged. Unpainted

Photograph Number: 6,7,8 Drawing Number: 1,3

Describe work and impact on existing feature:

The cabinets will be replaced with new off the shelf cabinets and appliances.

FEATURE 3

Feature: Southwest Room

Approximate date of feature: unknown

Describe existing feature and its condition:

The room is gutted and a wall is inadequately supported. Photograph Number: 9,10 Drawing Number: 1,3

Describe work and impact on existing feature:

Drywall, paint and trim with style matching existing rooms.

FEATURE 4

Feature: First floor bathroom Approximate date of feature: 1970

Describe existing feature and its condition:

Functioning hatchroom with ca 1970 style color, tile and off

the shelf appliances

Photograph Number: 11 Drawing Number: 1,3

Describe work and impact on existing feature:

retile and install modern appliances. The claw food bath tub from the second floor will be refinished and relocated here

FEATURE 5

Feature: Fire place decorative column in dining room

Approximate date of feature: unknown

Describe existing feature and its condition:

the left column is missing

Photograph Number: 12 Drawing Number: 1,3

Describe work and impact on existing feature:

copy the column on the right to replace the left hand column.

FEATURE 6

Feature: East side second floor bathroom Approximate date of feature: 1970

Describe work and impact on existing feature: ON F LE remodel bathroom per CONPOSITE EXHIBIT 1
PAGE 4 OF 85

Describe existing feature and its condition:

Functional bathroom with ca 1970s paneling, tile and off the I moved to the first floor bathroom. shelf appliances and period clawfoot bath tub.

Photograph Number: 13,14 Drawing Number: 1,3

claw, foot bathtub will be refurbished and

FEATURE 7

Feature: Second floor shower Approximate date of feature: 1970

Describe existing feature and its condition:

non functioning shower room with tiled floor and wall appears to bhave been a failed attempt to convert a closet into shower

Photograph Number: 15 Drawing Number: 2,4

Describe work and impact on existing feature:

revert to the original closet. Remove tile and plumibn. Fit interior with drywall. Retain octogonal windows.

FEATURE 8

Feature: upstairs hallway

Approximate date of feature: unknown

Describe existing feature and its condition:

The walls are angled, probably to provide room for a closet in the south west corner after the original closet was converted to a shower.

Photograph Number: 16 Drawing Number: 2,4

Describe work and impact on existing feature:

Remove the closet at the east side of the wall per attached drawing.

FEATURE 9

Feature: master bath

Approximate date of feature: 1970

Describe existing feature and its condition:

Non functioning bathroom appears to be added ca 1970

based on style and color.

Photograph Number: 17 Drawing Number: 2,4

Describe work and impact on existing feature:

demolish barthroom. Create laundry room per drawing. Window and doors will not be altered

FEATURE 10

Feature: closets between north and middle room on the west side of second floor

Approximate date of feature: unknown.

Describe existing feature and its condition:

functioning closets, based on door style and sizes used in

some of the closet added later.

Photograph Number: 20,19 Drawing Number: 2,4

Describe work and impact on existing feature:

remove closets, open door per drawing. Reuse existing door if possible.

FEATURE 11

Feature: 2nd Floor south west bedroom Approximate date of feature: unknown

Describe existing feature and its condition:

This bedroom was likely created in an earlier remodel. It has its own heat source (a wall mounted gas heater) which was Describe work and impact on existing feature:

remodel into bathroom per drawing. Removegas heater. Add connecting door to middle room

COMPOSITE EXHIBIT 1

PAGE 5 OF 85

popular around 1970.

Photograph Number: 21,22,23,24 Drawing Number: 2,4

FEATURE 12

Feature: All Windows

Approximate date of feature: various

Describe existing feature and its condition:

windows from various periods around the house. The condition of the windows varies but most suffer from broken pulleys, flaking paint, broken panes, rusted and missing hard

ware, wood rot and termite damage

Photograph Number: 25-52 Drawing Number: 1,2,3,4

Describe work and impact on existing feature:

restore all windows, replace wood-as needed. Make windows functional if possible. Paint windows and replace or repair hardware.

FEATURE 13

Feature: Backdoor / Frontdoor

Approximate date of feature: unknown

Describe existing feature and its condition:

Doors from various periods with wood rot and termite damge. Hardware is partially missing, broken or doesn't fit.

Locks don't close properly. Peeled paint

Photograph Number: 54 Drawing Number: 1,3

Describe work and impact on existing feature:

The doors will be restored and wood rot will be repaired. Hardware will be adjusted or replaced as needed. Doors will be painted.

FEATURE 14

Feature: Exterior wood and Paint Approximate date of feature: N/A

Describe existing feature and its condition:

The outside of the building suffers from wood rot, termite

damage and is not painted.

Photograph Number: 28,38 ... Drawing Number:

Describe work and impact on existing feature:

missing wood will be replaced with identical dimensioned wood. Building will be painted.

FEATURE 15

Feature: upstairs tower

Approximate date of feature: unknown

Describe existing feature and its condition:

The room above the tower and the master bedroom were combined at some point and are now seperated by an

opening with modern (ca. 1990) colums.

Photograph Number: 18 Drawing Number: 1,3

Describe work and impact on existing feature:

The two rooms will be seperated by a wall to reflect the floorplan still visible downstairs.

FEATURE 16

Feature:

Approximate date of feature:


Describe existing feature and its condition:

Photograph Number:


Drawing Number:

Describe work and impact on existing feature:


ON FILE COMPOSITE EXHIBIT 1 PAGE 6 OF 85




Drawing 1: Current State of Frist Floor




Drawing 2: Current state of 2nd floor



Drawing 3: Modified 1st Floor



Drawing 4: Modified 2nd floor



COMPOSITE EXHIBIT 1
PAGE 11 OF 85





Picture 1: Property featured on Page 183 of "Jacksonville's Architectural Heritage", published by University Press of Florida.




Picture 2: View of 152 East 4th Street from corner of Market and 4th Street (December 2013)



Picture 3: View of east side of 152 East 4th Street (December 2013)



Picture 4: West side of 152 East 4th Street (December 2013)



Picture 5: Kitchen Door (east side, December 2013)



Picture 6: Inside Kitchen facing east. Door to outside is visible at the left side.



Picture 7: Inside Kitchen facing south.




Picture 8: kitchen facing west



Picture 9: South-West room facing south



Picture 10: South-West room ceiling



Picture 11: First floor bathroom




Photo 12: Fireplace West Middle Room



Photo 13: Second Floor East Bathroom



Photo 14: Second Floor East Bathroom facing north



Photo 15: Shower attached to 2nd Floor South-East Bedroom



Picture 16: Upstairs hallway facing the angled wall connecting the east bathroom and the south east bedroom.



Photo 17: 2nd Floor West bathroom



Photo 18: Opening connecting the two 2nd flor rooms at the north side of the house.



Photo 19: Closets at the southern wall of the 2nd floor north-west room.



Photo 20: 2nd Floor middle west room. Wall leading to north room.



Photo 21: 2nd Floor South-west bedroom from outside hallway facing south-west





Photo 22: 2nd Floor South West bedroom. Facing east,



Phoot 23: 2nd Floor South West bedroom facing south



Photo 24: 2nd Floor South West Bedroom facing west.




Photo 25: painted shut window west of entrance (1st floor)



Photo 26: 1st Floor porch center window. Window faces north.



Photo 27: 1st floor window at western end of porch. Window is painted shut and may not be operable.



Photo 28: 1st Floor window facing west. Window may not be operable. Missing panes.



Photo 29: Curved window on turret attached to west side of house. Window faces north-west. Window is not designed to open.



Photo 30: Curved window on west-side turret facing west. Window is paint shut not designed to open.



Photo 31: Curved Window on west-side turret facing south. Window is not paint shut / not designed to operate.




Photo 32: Window to the left of entrance door, facing approx.. north. Window panes appear modern. Paint shut.



Photo 33: Stained glass window at Northeast corner of first floor. The window is protected by Plexiglas and not designed to be opened.



Photo 34: 1st floor window facing east. This window is part of the turret at the north-east corner.



Photo 35: Stained glass windows at the east side of the house. These windows are placed at the landing of the stair case between first and second floor. The windows




Photo 36: Bathroom window to the right of the kitchen door. The window has been replaced, but some original trim remains.




Photo 37: Kitchen Window facing east. The window has been replaced but some original trim remains.




Photo 38: 1st floor kitchen window facing south. The window has been replaced but some original trim remains.



Photo 39: 2nd floor southwest bedroom window facing south. The window has been paint shut and may or may not operate.




Photo 40: Shower/closet attached to south side of 2nd floor. The windows are fixed and can not be opened.



Photo 41: Shower/closet attached the south side of 2nd floor. View from the east. The window is fixed and can not be opened.



Photo 42: East facing window to the 2nd floor southeast bedroom.




Photo 43: Window to the 2nd floor east bathroom. Glass broken, window currently not operable.




Photo 44: Window of the 2nd floor turret facing east. Panes are broken and window is paint shut. May not operate.




Photo 45: Window of 2nd floor turret facing northeast. Panes are broken and window is pain shut. May not operate.



Photo 46: Window on 2nd floor of turret facing northwest. Window pane is broken and window is paint shut. It may not operate.



Photo 47: 2nd floor diamond shape window facing north right next to the turret above main entrance. The window is not designed to operate.



Photo 48: 2nd floor northwest room facing south. This window is partially operational but some hardware is missing. (to the left of the window shown in Photo 49).



Photo 49: 2nd floor window to the northwest room facing north (to the right of the window shown in Photo 48). The window is partially operational but missing hardware.




Photo 50: 2nd floor diamond shape window to the northwest room. This floor is not designed to be opened.



Photo 51: 2nd floor diamond shape window to the north west room facing west. The window is not designed to be opened.




Photo 52: 2nd floor round window to the middle room. This window is not designed to be opened.



Photo 53: Windows of the turret facing the corner of Market Street and 4th Street (northeast corner of house). These window open to the attic and are not operational.



Photo 54: Backdoor at the south side of the house. The door is currently a functional off the shelf door.

ZHONG HAILING * PO BOX 13314 JACKSONVILLE, FL 32206

Primary Site Address 152 E 4TH ST Jacksonviile FL 32206 Official Record Book/Page 16575-02034

Tile # 6412

152 E 4TH ST

Property Detail

RE#	070928-0000
Tax District	USD1
Property Use	0810 RESIDENTIAL UNITS 2-9
# of Buildings	2
Legal Desc.	2-4 37-2S-26E .215 SPRINGFIELD
Subdivision	01188 SRINGFELD S/D BLK 3,5,9,
Total Area	9296
Characteristics	Historic Designation

The sale of this property may result in higher property taxes. For more information go to <u>Save Our Homes</u> and our <u>Property Tax Estimator</u>. Property values, exemptions and other information listed as 'In Progress' are subject to change. These numbers are part of the 2014 working tax roll and will not be certified until October. <u>Learn how the</u> Property Appraiser's Office values property.

Vaiue Summary

	2013 Certified	2014 In Progress
Value Method	CAMA	CAMA
Total Building Value	\$110,962.00	\$120,097.00
Extra Feature Value	\$1,131.00	\$1,131.00
Land Value (Market)	\$18,225.00	\$18,225.00
Land Value (Agric.)	\$0.00	\$0.00
Just (Market) Value	\$130,318.00	\$139,453.00
Assessed Value	\$130,318.00	\$139,453.00
Cap Diff/Portability Amt	\$0.00 / \$0.00	\$0.00 / \$0.00
Exemptions	\$0.00	See below
Taxable Value	\$130,318.00	See below

Taxable Values and Exemptions - In Progress †

If there are no exemptions applicable to a taxing authority, the Taxable Value is the same as the Assessed Value listed above in the Value

County/Municipal Taxable Value SJRWMD/FIND Taxable Value No applicable exemptions

No applicable exemptions

School Taxable Value No applicable exemptions

Sales History

Book/Page	Sale Date	Sale Price	Deed Instrument Type Code	Qualified/Unqualified	Vacant/Improved
16575-02034	10/25/2013	\$100,000.00	SW - Special Warranty	Unqualified	Improved
16575-02032	6/26/2013	\$100.00	WD - Warranty Deed	Unqualified	Improved
16159-00454	11/26/2012	\$67,800.00	CT - Certificate of Title	Unqualified	Improved
15013-01070	11/25/2003	\$100.00	WD - Warranty Deed	Unqualified	Improved
11551-00390	11/25/2003	\$239,000.00	WD - Warranty Deed	Unqualified	Improved
11462-00156	10/9/2003	\$100.00	QC - Quit Claim	Unqualified	Improved
10640-00198	5/1/2002	\$100.00	WD - Warranty Deed	Unqualified	Improved
10307-01378	1/2/2002	\$200,000.00	WD - Warranty Deed	Unqualified	Improved
08966-02333	6/3/1998	\$100.00	MS - Miscellaneous	Unqualified	Improved
07769-00612	1/31/1994	\$127,000.00	WD - Warranty Deed	Qualified	Improved
06342-01069	6/2/1987	\$33,500.00	WD - Warranty Deed	Unqualified	Improved
05896-02204	12/27/1984	\$100.00	QC - Quit Claim	Unqualifled	Improved
04637-00081	5/11/1978	\$100.00	MS - Miscellaneous	Unqualified	Improved

Extra Features

LN	Feature Code	Feature Description	Bldg.	Length	Width	Total Units	Value
1	FPMR7	Fireplace Masonry	1	0	0	2.00	\$1,131.00

Land & Legal

عل	Land								
LI		,		t :	Depth	Category	Land Units	Land Type	Land Value
1	0101	RES MD 8-19 UNITS PER AC	RMD-S	90.00	104.50	Common	90.00	Front Footage	\$18,225.00

<u>Leg</u>	Legal					
LN	Legal Description					
1	2-4 37-25-26E .215					
2	SPRINGFIELD					
3	E 90FT OF N 1/2 LOT 2					
4	BLK 13					

Buildings + Building 1 Building 1 Site Address 152 E 4TH ST

Element	Code	Detail	
		1	

http://apps.coj.net/pao_propertySearch/Basic/Detail.aspx?RE=070page#d62044

acksonville FL 32	206			Exte	rior Wall	4	4 Single Siding		т
Building Type		0102 - SFR 2 S	TORY	Roof	ing Structure	3	3 Gable or Hip		ألبا
Year Built		1909	STUKT	Roof	ing Cover	12	12 Modular Metal		BALIUC
1 4 1 1 1 1 1 1 1 1 1 1 1 1 1				Inter	rior Wall	3	3 Plastered		
Building Value		\$99,637.00		Inter	rior Wall	5	5 Drywall	1 8 1	<u> </u>
	T	1	1	Int F	looring	9	9 Pine / Soft Woods	H-UA:BAS	
Туре	Gross	Heated Area	Effective Area	Int F	looring	11	11Ceramic Clay Tile		
Balcomi	1			Heat	ing Fuel	4	4 Electric		
Balcony	143	0	21	1 1 1 1 1 1 1 1 1	ing Type	4	4 Forced-Ducted		
Unfinished Storage	143	0	57	495 1000	anditioning	3	3 Central	Building 2	
Balcony	1177	0	177	_			J CCIIBAI		
Unfinished Carport	1177	0	235	Elen	nent	Code			
Unfin Open Porch	160	0	32	Stori	es coms	2.000		_	
Addition	160	160	144	Bath		3.000		<u>N</u>	
Finished upper	-	100	144		ns / Units	1.000		14	
story 1	1144	1144	1087		ns / UIRES	1.000	1		
Base Area	1144	1144	1144	Building 2	Site Address				
Base Area	168	168	168	1344 MARI	KET ST				
Finished Open Porch	60	0	18	Jacksonvill	e FL 32206-				
Base Area	60	60	60	Building	Туре	0101 - SFR 1	STORY		
Finished Open Porch	13	0	4	Year Bui Building	A CONTRACTOR OF THE PARTY OF	1953			
Unfin Open	40 144			Dulloting	- value	\$20,460.00			
Porch	18	0	4		la	140 - 4	L		
Unfin Open Porch	91	0	18	Туре	Gross Area	Heated Area	Effective Area		
Finished upper	- 1 1100	North Control of State		Addition	342	342	308		
story 1	20	20	19	Base	380	380	380		
Base Area	55	55	55	Area					
Finished Open Porch	188	0	56	Total	722 nent	722 Code	688 Detail		
Total	5921	2751	3299		rior Wall	7	7 Cem Fib Shing		
				- <u>}-</u>	nor Wall	15	15 Concrete Bik	ADT	
					ing Structure	3		-	
				1,000	The second second		3 Gabie or Hip		
					ing Cover	3	3 Asph/Comp Shingle	'	
					rlor Wall	5	5 Drywall	BAS	į.
					looring	2	2 Min / Plywood		Ì
					Tooring	1	1 None		
				Heat	ing Fuel	4	4 Electric	1	
				Heat	ling Type	3	3 Forced-Not Ducted	307	
				Air C	onditioning	2	2 Wall Unit		
				E1==	nent	Code		٦	
				1		Code	1		
				Stor		1.000			
					rooms	2.000		***	
				Bath	S	1.000	services and the services of the	0.7	
					ms / Units		The state of the s		

Traversing Data

ADT:0,18:=E19 N18 W19 S18 \$ BAS:0,18:=S20 E19 N20 W19 \$.

2013 Notice of Proposed Property Taxes (Truth in Millage Notice)							
Taxing District	Assessed Value	Exemptions	Taxable Value	Last Year	Proposed	Rolled-back	7
		1	Ti-	Es.	10		ŀ

http://apps.coj.net/pao_propertySearch/Basic/Detail.aspx?RE=070page46062014

Current Year	\$130,318.00	\$130,318.00		\$0.00	\$130,318	
Last Year	Just Value \$178,027.00	\$178,027.00		Exemptions \$0.00	\$178,027.	4-11
			Totals	\$3,204.67	\$2,513.32	\$2,381.07
Urb Ser Dist1 Voted	\$130,318.00	\$0.00	\$130,318.00	\$0.00	\$0.00	\$0.00
School Board Voted	\$130,318.00	\$0.00	\$130,318.00	\$0.00	\$0.00	\$0.00
Gen Gov Voted	\$130,318.00	\$0.00	\$130,318.00	\$0.00	\$0.00	\$0.00
Water Mgmt Dist. SJRWMD	\$130,318.00	\$0.00	\$130,318.00	\$58.98	\$42.78	\$42.78
FL Inland Navigation Dist.	\$130,318.00	\$0.00	\$130,318.00	\$6.14	\$4.50	\$4.33
By Local Board	\$130,318.00	\$0.00	\$130,318.00	\$400.20	\$292.95	\$296.77
Public Schools: By State Law	\$130,318.00	\$0.00	\$130,318.00	\$952.80	\$669.83	\$706.55
Urban Service Dist1	\$130,318.00	\$0.00	\$130,318.00	\$0.00	\$0.00	\$0.00
Gen Govt Ex B&B	\$130,318.00	\$0.00	\$130,318.00	\$1,786.55	\$1,503.26	\$1,330.64

Property Record Card (PRC)
The Property Appraiser's Office (PAO) provides historical property record cards (PRCs) online for 1995-2005. The PAO no longer maintains a certified PRC file due to changes in appraisal software; therefore, there are no PRCs available online from 2006 forward. You may print this page which provides the current property record. (Sections not needed can be minimized.) To print the past-year cards below, set your browser's Page Set Up for printing to Landscape.

2005 | 2004 | 2003 | 2002 | 2001 | 2000 | 1999 | 1998 | 1997 | 1996 | 1995

More Information

Contact Us | Parcel Tax Record | GIS Man | Map this property on Google Maps | City Fees Record

PRE-CONSTRUCTION APPLICATION REVIEW

For Local Historic Preservation Office or Division Use Only

Proper	erty Identification Number: 070928-0000					
Proper	erty Address: 152 East 4th Street					
The 🔀	Local Historic Preservation Office/ Division has reviewed Partoperty Tax Exemption Application for the above named property at the property and property are property as a property at the	t 1 (Preconstruction Application) of the Historic Preserva-				
	Certifies that the above referenced property <i>qualifies</i> as a historic <i>F. S.</i>					
	Certifies that the above referenced property <u>does not qualify</u> as a 196.1997(11) F. S	historic property consistent with the provisions of				
	Certified that the above referenced property <i>qualifies</i> for the special exemption provided under \$196.1998, F.S., for properties occupied by non-profit organizations or government agencies and regularly open to the public.					
	Certified that the above referenced property does not qualify for					
	Determines that improvements to the above referenced property a Rehabilitation and Guidelines for Rehabilitating Historic Buildi	ma annulatura vita di di				
	Determines that improvements to the above referenced property a for Rehabilitation and Guidelines for Rehabilitating Historic Bu	ma mad according to the same				
	All work not consistent with the referenced standards and guideling					
	Recommendations to assist the applicant in bringing the proposed lines and criteria are provided in the Review Comments.	work into compliance with the referenced standards, guide-				
	Review Comments: INITIAL INSPECTION 12/17/13	-2D				
	Additional Review Comments attached? Yes No	rature				
	Tit	nted Name: <u>LISA SHEPPARD</u> le: <u>SENIOR HISTORIC PRESERVATION PLANNER</u> te: <u>4/1/14</u>				

Street:

City: ____, State: ____ Zip Code: _

Social Security or Taxpayer Identification Number:

HISTORIC PRESERVATION PROPERTY TAX EXEMPTION APPLICATION PART 2--REQUEST FOR REVIEW OF COMPLETED WORK

INSTRUCTIONS: Upon completion of the restoration, rehabilitation or renovation, return this form with photographs of the completed work (both exterior and interior views for buildings) to the Division of Historical Resources or the Local Historic Preservation Office, as applicable. These photographs must provide a comprehensive description of the completed work. They should be the same views as the before photographs included in the Pre-construction Application. Type or print clearly in black ink. The final recommendation of the Division of Historical Resources or the Local Historic Preservation Office, as applicable with respect to the requested historic preservation property tax exemption is made on the basis of the descriptions in this Request for Review of Completed

WOIK.					
1.	Property Identification and Location:				
	Property Identification Number: 070928-0000				
	Address of property: 152 E 4th st. Jacksonville FL 32206				
	City: Jacksonville, County: duval Zip Code: 32206				
2.	Data on restoration, rehabilitation or renovation project:				
	Project starting date: March 06, 2014 Project completion date: June 04, 2015				
	Estimate cost of entire project: \$262,997.88				
	Estimated costs attributed solely to work on historic buildings or archaeological sites: \$250,067.88				
3.	Owner attestation: I hereby apply for the historic preservation property tax exemption for the restoration, rehabilitation or renovation work described above and in the Preconstruction Application for this project which received approval on February 03, 2014. I hereby attest that the information provided is, to the best of my knowledge, correct, and that in my opinion the completed project conforms to the Secretary of the Interior's Standards for Rehabilitation and Guidelines for Rehabilitating Historic Buildings, and is consistent with the work described in the Preconstruction Application. I also attest that I am the owner of the property described above or, if the property is not owned by an individual, that I am the duly authorized representative of the owner. Further, by submission of this application, I agree to allow access to the property by representatives of the Division of Historical Resources or the Local Historic Preservation Office, where such office exists, and appropriate representatives of the local government from which the exemption is being requested, for the purpose of verification of information provided in this application. I understand that, if the requested exemption is granted, I will be required to enter into a Covenant with the local government granting the exemption in which I must agree to maintain the character of the property and the qualifying improvements for the term of the exemption. I also understand that falsification of factual representations in this application is subject to criminal sanctions, pursuant to the Laws of Florida.				
	Name: Hailing Zhong Signature: Date: Oct 28, 2015				
	Complete the following, if signing for an organization or multiple owners (see additional owners below):				
	Title: Organization:				
	Social Security or Taxpayer Identification Number:				
	Mailing Address:				
	City:, State: Zip Code:				
	Daytime Telephone Number: ()				
	•				
	List Additional Owners:				
	Name:				
	· ·				

If there are additional owners, provide the indicated information for each on a separate sheet of paper.

ON FILE


COMPOSITE EXHIBIT 1 PAGE 43 OF 85



Picture 1: Property featured on Page 183 of "Jacksonville's Architectural Heritage", published by University Press of Florida.



Picture 2: View of 152 East 4th Street from corner of Market and 4th Street (October 27, 2015)



Picture 3: View of east side of 152 East 4th Street (October 27, 2015)



Picture 4: West side of 152 East 4th Street (October 27, 2015)



Picture 5: Kitchen Door (east side, October 27, 2015)




Picture 6: Inside Kitchen facing east. Door to outside is visible at the left side.



Picture 7: Inside Kitchen facing south.



Picture 8: kitchen facing west



Picture 9: South-West room facing south



Picture 10: South-West room ceiling



Picture 11: First floor bathroom



Photo 12: Fireplace West Middle Room



Photo 13: Second Floor East Bathroom



Photo 14: Second Floor East Bathroom facing north



Photo 15: Shower attached to 2nd Floor South-East Bedroom



Picture 16: Upstairs hallway facing the angled wall connecting the east bathroom and the south east bedroom.



Photo 17: 2nd Floor was West bathroom, now laundry room



Photo 18: Opening connecting the two 2nd floor rooms at the north side of the house.



Photo 19: Closets at the southern wall of the 2nd floor north-west room.



Photo 20: 2nd Floor middle west room. Wall leading to north room.



Photo 21: 2nd Floor was South-west bedroom, now bathroom, view from outside hallway facing south-west



Photo 22: 2nd Floor was South West bedroom now bathroom. View by Facing east.



Phoot 23: 2nd Floor was South West bedroom now bathroom, view by facing south



Photo 24: 2nd Floor was South West Bedroom now bathroom, view by facing west.



Photo 25: was painted shut window west of entrance, now restored and fully operational (1st floor)



Photo 26: 1st Floor porch center window. Window faces north.



Photo 27: 1st floor window at western end of porch. Window was painted shut now restored and operational.



Photo 28: 1st Floor window facing west. Window restored and operational



Photo 29: Curved window on turret attached to west side of house. Window faces north-west. Window is not designed to open.



Photo 30: Curved window on west-side turret facing west. Window is paint shut not designed to open.



Photo 31: Curved Window on west-side turret facing south. Window is paint shut / not designed to operate.



Photo 32: Window to the left of entrance door, facing approx.. north. Window panes appear modern. Was paint shut, now operational



Photo 33: Stained glass window at Northeast corner of first floor. The window is protected by Plexiglas and not designed to be opened.



Photo 34: 1st floor window facing east. This window is part of the turret at the north-east corner.



Photo 35: Stained glass windows at the east side of the house. These windows are placed at the landing of the stair case between first and second floor. The windows do not open.



Photo 36: Bathroom window to the right of the kitchen door. The window has been replaced, but some original trim remains.








Photo 38: 1st floor kitchen window facing south.



Photo 39: 2nd floor southwest bedroom window facing south. The window has been paint shut now operational.




Photo 40: Shower/closet attached to south side of 2nd floor. The windows are fixed and can not be opened.



Photo 41: Shower/closet attached the south side of 2nd floor. View from the east. The window is fixed and can not be opened.



Photo 42: East facing window to the 2nd floor southeast bedroom.



Photo 43: Window to the 2nd floor east bathroom. Glass was broken, window now restored and operational.




Photo 44: Window of the 2nd floor turret facing east. Panes were broken and window was paint shut. Now restored and operational.




Photo 45: Window of 2nd floor turret facing northeast. Panes were broken and window was pain shut. Now restored and operational.



Photo 46: Window on 2nd floor of turret facing northwest. Window pane was broken and window was paint shut. Restored and operational.



Photo 47: 2nd floor diamond shape window facing north right next to the turret above main entrance. The window is not designed to operate.



Photo 48: 2nd floor northwest room facing south. This window was partially operational but some hardware was missing. Now restored and operational (to the left of the window shown in Photo 49).



Photo 49: 2nd floor window to the northwest room facing north (to the right of the window shown in Photo 48). The window was partially operational but missing hardware. Now restored and operational.



Photo 50: 2nd floor diamond shape window to the northwest room. This floor is not designed to be opened.




Photo 51: 2nd floor diamond shape window to the north west room facing west. The window is not designed to be opened.




Photo 52: 2nd floor round window to the middle room. This window is not designed to be opened.



Photo 53: Windows of the turret facing the corner of Market Street and 4th Street (northeast corner of house). These window open to the attic and are not operational.



Photo 54: Backdoor at the south side of the house. The door is currently a functional off the shelf door. It is repainted.

REVIEW OF COMPLETED WORK

For Local Historic Preservation Office or Division Use Only

	201 Estat Historic Preservation Office or Division Use Only
Proper	ty Identification Number: 070928-0000
	ty Address: 152 East 4th Street
The 🔀 ic Prese	Local Historic Preservation Office/ Division has reviewed Part2 (Request for Review of Completed Work) of the Histor relation Property Tax Exemption Application for the above named property and hereby:
	Determines that the completed improvements to the above referenced property <u>are consistent</u> with the Secretary of the Interior's Standards for Rehabilitation and Guidelines for Rehabilitating Historic Buildings and the criteria set forth in Chapter 1A-38, F.A.C., and, therefore, <u>recommends approval</u> of the requested historic preservation tax exemption.
	Determines that the completed improvements to the above referenced property <u>are not consistent</u> with the Secretary of the Interior's Standards for Rehabilitation and Guidelines for Rehabilitating Historic Buildings, and the criteria set forth in Chapter 1A-38, F.A.C., and, therefore, <u>recommends denial</u> of the requested historic preservation tax exemption for the <u>reasons stated in the Review Comments below</u> :
	Review Comments: COA-13-877 (REROOF) COA-14-254 (EXTERIOR REPAIRS/REPAINT) COA-15-349(FENCING REPAIRS) COA-15-356.(DOORS) INSPECTED 6/6/15 Additional Review Comments attached? Yes No

Printed Name: <u>LISA SHEPPARD</u>
Title: <u>SENIOR HISTORIC PRESERVATION PLANNER</u>

Date: 10-30-15

DEPARTMENT OF PLANNING AND DEVELOPMENT

Building Inspection Division



The City of Jacksonville hereby issues a Certificate of Completion at the below listed address:

FOR PROPERTY AT:

CONTRACTOR:

152 4TH Street East

Glory Homes, Inc

JACKSONVILLE, FL 32206

7027 Alpine Street Jacksonville, FL 32208

RE# 070928 0000

Permit #: B-14-613909.000

OWNER:

Residential Single Family Alterations & Repairs

Hailng Zhong

152 E 4TH ST

JACKSONVILLE, FL 32206-4524

This is to certify that the Building Inspection Division has inspected and approved the construction of the work as identified by the permit above.

6/4/2015

Certificate Issued Date

Tom Goldsbury, C.B.O. Building Official

JIH Soldale

Glory Homes Inc.

904 838-0057 gloryhomes2000@gmail.com

Office: 7027 Alpine Street Jacksonville FL 32208 Shop: 2016 Walnut Jacksonville, FL, 32206

October 28, 2015

RE: Cost to renovate 152 East 4th St

Client: Hailing Zhong

To summarize, the total cost of the restoration work done by Glory Homes on 152 East 4th St was \$ 250,067.88. This includes all labor provided by Glory Homes, all sub-contracts through Glory Homes and all materials provided by Glory Homes. In addition, the knee wall and carport work was another \$ 4,800.00.

Joseph J Markusic Vice President Glory Homes, Inc.

CBC059741

Giory Homes, inc. CBC059741 7027 Alpine St Jacksonville Florida 32208 Shop: 2018 Walnut St.

Administration

Professional Admin Admin	Professiona Admin Admin	Professiona	Professiona	Professiona	<u></u>	Admin	CO	Admin	င်ဝ	Admin	Data Name	
Allowance for supervision of Lab Project clean up and safety of Lab			! L	_ L		Puli COA	NOC	Meet inspectors	Permit estimated costs	Puli city permit	Task	
of Labor & Sub of Labor	of Labor & Sub	of Labor & Sub		1		0.5			_	1.5	Total Time	
10.00%	10.00%	10.00%			\$100.00	\$46.00	\$11.00	\$46.00	\$1,078.50	,	Our Rate	
\$100.00 \$0.00 \$16,634.11 \$0.00 \$0.00	\$100.00 \$0.00 \$16,634.11 \$0.00	\$100.00 \$0.00 \$16,634.11	\$0.00	\$100.00		\$23.00	\$11.00	\$0.00	\$1,078.50	\$69.00	Our Cost	
60 60 60		<u> </u>	\$1,281.50		\$1.281.50	\$1,181.50	\$1,158.50		ļ		Total	

Admin

Johannes Ulirich
Project:
152 East 4th St
Historic Springfield, FL

ON FILE COMPOSITE EXHIBIT 1 PAGE 74 OF 85

CBC059741 Shop: 2018 Walnut St. 7027 Alpine St Jacksonville Florida 32208

Glory Homes, Inc.

Time

1/2015	Cody Lovelace	Fence, demo lattice, sofit vents	6.25	\$20.50	\$128.13	\$115,953.83
1/2015	Jackie Minor	clean bricks	4	\$15.50	\$62.00	\$116,015.83
1/2015	Doug Pruitt	Painting	00	\$17.50	\$140.00	\$116,155.83
21/2015	Dale Baker	Painting	8	\$19.50	\$156.00	\$116,311.83
		Seal Porch	3	\$16.50	\$49.50	\$116,361.33

05/2

05/27/2015

05/28/2015

05/22/2015

05/22/2015

Donaid Nacoste

05/22/2015 | Jackie Minor

_	
1: Historic S	
152 E Sprir	
Project: 152 East 4th St Springfield, FL	
다. 다. 다. 다. 다. 다. 다.	
ON FIL	E

Johannes Ulirich

Hailing Zhong

COMPOSITE EXHIBIT 1 PAGE 75 OF 85

7.5

თ (J)

\$17.50 \$17.50

> \$105.00 \$140.00 \$140.00 \$140.00 \$132.00 \$132.00

\$119,159.45 \$119,054.45

\$92.50 146.25

\$119,485.70 \$119,339.45 \$87.50

\$119,246.95

œ œ œ œ œ

06/09/2015 05/29/2015

Kevin Adams

Poly Floors

Electrical finish work

Mac

06/03/2015 06/02/2015 06/01/2015 05/29/2015 06/04/2015 06/03/2015

Painting Painting Painting Painting

Painting

Doug Pruitt

Doug Pruitt

Doug Pruitt

Donaid Nacoste

yard work, cleaning inside & outside

yard work, cleaning inside & outside

06/04/2015

Doug Pruitt Doug Pruitt 05/31/2015 05/30/2015 06/04/2015

06/02/2015

Donaid Nacoste

yard work, cleaning site

Donaid Nacoste

05/20/2015 05/19/2015

6 ΚB 05/22/2015

Dale Baker

Paint

6.5

\$21.50

\$21.50

œ œ œ Ç œ

\$17.50

\$17.50 \$17.50 \$17.50

\$19.50

\$126.75

\$117,339.83

\$140.00 \$117,213.08 \$140.00 \$117,073.08 \$140.00 \$116,933.08

\$21.50

\$172.00 \$117,511.83

\$117,683.83

\$117,855.83

Painting Painting Painting

Stucco perimeter waii

05/28/2015 05/27/2015 05/28/2015 05/25/2015

Doug Pruitt

Doug Pruitt

Doug Pruitt

Doug Pruitt Doug Pruitt Donaid Nacoste Donald Nacoste

Painting

Painting

Remove Trash & clean inside

5.75

\$17.50

\$140.00

\$116,740.58

\$94.88 \$116,600.58

\$49.50 \$116,410.83

\$116,505.70

\$52.50 \$116,793.08

\$16.50

\$16.50 \$16.50

5.75

Cieaning outside Laying Paper Seal Porch

05/21/2015

大 B

Stucco perimeter wall Stucco perimeter wall

Cody Lovelace

Donald Nacoste

Donald Nacoste

Yard work

5.75

œ 00 œ œ œ

7.5

\$123.75

\$132.00 \$164.00 \$172.00 \$172.00

\$118,019.83

\$94.88

\$16.50 \$16.50 \$16.50 \$16.50 \$16.50 \$20.50

\$118,774.45

\$118,634.45 \$118,502.45 \$118,370.45 \$118,246.70 \$118,151.83

\$118,914.45

\$17.50 \$17.50

\$17.50

Yard work **Punch List**

Glory Homes, inc. CBC059741 7027 Alpine St Jacksonville Florida 32208 Shop: 2018 Wainut St.

Time

\$119,761.70	\$120.00	\$24.00	ch	Build custom capitals	Phii N	8/2014
\$119,641.70						
\$119,641.70	\$156.00	\$19.50	8	Poly Floors	0/2015 Kevin Adams	0/2015

4.25

5.5

\$24.00

\$144.00 \$132.00

\$120,139.70

\$24.00

\$119,995.70

\$119,863.70

\$24.00

\$144.00

\$120,427.70

\$144.00 \$120,283.70

Historic Springfield, FL 152 East 4th St

Project:

Hailing Zhong Johannes Ullrich ON FILE **COMPOSITE EXHIBIT 1**

PAGE 76 OF 85

_
ਲ
黑
ŏ
မ္ဟ
Ċ

03/25/2014

Special Credit

Account for window time issues

Labor accumulated of 3 weeks -

48

\$24.00

\$1,152.00

\$123,325.70

\$123,325.70

\$5,245 00

\$5,245.00

\$118,080.70

06/02/2015

Joe M

02/12/2015 02/11/2015

Phii N Phii N Phii Z

Build Mantei Build Mantel Build Mante Build Mantel Build Mantei Build Mantel Build Mantel Bulid Mantei Build Mantel Build Mantel Build Mantel Build Mantel **Build Mantel Build Mantel Build Mantel Build Mantel**

02/10/2015

02/09/2015 02/05/2015 02/03/2015

Phii Z Phii N

3.75

\$24.00 \$24.00

\$24.00

\$24.00

\$72.00 \$12.00 \$96.00

\$122,173.70

\$122,173.70

\$122,101.70

\$122,089.70 \$121,993.70 \$121,903.70 \$121,807.70

4.5

\$24.00 \$24.00 \$24.00 \$24.00 \$24.00 \$24.00 \$24.00 \$24.00

\$108.00

\$96.00

\$121,699.70

\$120.00 \$120.00 \$126.00

\$121,603.70 \$121,483.70 \$121,363.70

\$24.00

\$90.00

\$96.00

0.5

ယ

01/30/2015

Phii N Phil Phii N Phii N Phil N

01/28/2015

01/27/2015 01/26/2015 01/23/2015 01/22/2015 01/16/2015 01/14/2015

Phii N

12/17/2014 Phil N 12/02/2014 12/01/2014

Phii N

Phii N Phii Z

Build custom capitals Build custom capitais Build custom capitals Build custom capitals Build custom capitals Build custom capitais Build custom capitals Build custom capitals

4.25

\$24.00 \$24.00 \$24.00 \$24.00

> \$102.00| \$120,673.70 \$144.00 \$120,571.70

\$24.00 \$120,697.70

O თ Ф O

11/26/2014 11/25/2014

Phii N

1/24/2014 1/21/2014

Phii N

Phii N

1/20/2014 Phil N 1/18/2014 Phil N

Phii Z

01/20/2015

Phii N

Phii N

5.25

Oi Ch 5.25

\$126.00 \$120.00 \$138.00 \$108.00

\$121,189.70

\$121,063.70

\$48.00

\$121,237.70

5.75

\$24.00 \$24.00

\$120,943.70 \$120,805.70

O

4.5

Phii N

Giory Homes, Inc. CBC059741 7027 Alpine St Jacksonville Florida 32208 Shop: 2018 Walnut St.

Time

3743 474.65 \$118,080.70 \$118,080.70 \$118,080.70

Final Total

2321

\$115,759.70

Project: 152 East 4th St Historic Springfield, FL ON FILE COMPOSITE EXHIBIT 1 PAGE 77 OF 85

Hailing Zhong Johannes Ullrich

Glory Homes, inc. CBC059741 7027 Alpine St Jacksonville Florida 32208 Shop: 2018 Walnut St.

	\$29,620.69					
	\$29,620.69	\$18.44	Winnseison	Piumbng parts	Exterior	06/03/2015
	\$29,602.25	\$114.28	Brinton's	Paint	interior	05/27/2015
	\$29,487.97	\$12.38	PB	Cleaning supplies	interior	05/27/2015
	\$29,475.59	\$15.95	Home Depot	Light Buibs	interior	05/26/2015
	\$29,459.64	\$58.73	Lowes	Spakie & Closet Parts	Interior	05/13/2015
	\$29,400.91	\$98.90	Home Depot	Light fixture, gas line, etc	Interior	05/20/2015
	\$29,302.01	\$28.89	Home Depot	Supplies	Interior	05/20/2015
	\$29,273.12	\$53.40	CLC	1x4 Trim	interior	05/19/2015
	\$29,219.72	\$383.42	Brinton's	Dry Erase Paint & Supplies	interior	05/21/2015
	\$28,836.30	\$23.18	PB	Paint, supplies, roof flashing	Exterior	05/21/2015
• • • • • • • • • • • • • • • • • • • •	\$28,813.12	\$3.52	PB	4" Brush	Exterior	05/20/2015
	\$28,809.60	\$4.59	PB	16 x 20 Glass	Exterior	05/20/2015
•	\$28,805.01	\$6.41	PB	16 x 24 Glass	Exterior	05/20/2015
	\$28,798.80	\$33.07	PB	Cleaning supplies & sandpaper	Exterior	05/19/2015
	\$28,765.53	\$9.94	BB	Supplies	Exterior	05/18/2015
	\$28,755.59	\$34.60	P8	Sandpaper & mortar	Exterior	05/18/2015
	\$28,720.99	\$217.66	Brinton's	Paint & Supplies	interior	05/18/2015
	\$28,503.33	\$69.66	CLC	Trim	Interior	05/18/2015
	\$28,433.67	\$51.07	Brinton's	Paint & Supplies	Interior	05/19/2015
	\$28,382.60	\$16.02	P8	Weather strip	interior	05/18/2015
	\$28,366.58	\$41.36	PB	dowel, roller catch, etc	Interior	05/15/2015
	\$28,325.22	\$3.95	PB	Door Vinyi	Interior	05/15/2015
	\$28,321.27	\$26.70	Brinton's	Paint	interior	05/15/2015
	\$28,294.57	\$22.17	P8	1x4x16s	Interior	05/07/2015
	\$28,272.40	\$51.96	Brinton's	Paint & Supplies	interior	05/20/2015
		\$59.28	PB	icemaker kit, etc	interior	05/13/2015
	\$28,161.16	\$171.90	Home Depot	Finish Electrical	interior	05/12/2015
- 300	\$27,989.26	\$19.27	PB	Finish Electrical	interior	05/11/2015
	\$27,969.99	\$23.52	P8	Bags	interior	05/09/2015
•						

Material

Project: 152 East 4th St Historic Springfield, FL Hailing Zhong Johannes Ulirich

ON FILE **COMPOSITE EXHIBIT 1** PAGE 78 OF 85

Glory Homes, Inc. CBC059741 7027 Alpine St Jacksonville Florida 32208 Shop: 2018 Walnut St.

-
\$
의
Ø
⊋.
쁘

\$29,597.37	-\$90.63	P8	Dura Rock	Credit	11/26/2014
\$29,688.00	-\$271.95	SH	17 pcs backerboard	Credit	11/25/2014
\$29,959.95	-\$18.14	GHI	bucket DW compound	Credit	11/25/2014
\$29,978.09					
\$29,978.09					
\$29,978.09	-\$176.00	Various	misc material not used	Credit	06/10/2015
\$30,154.09					
\$30,154.09					
\$30,154.09					
\$30,154.09					
\$30,154.09					
\$30,154.09					
\$30,154.09					
\$30,154.09					
\$30,154.09	\$66.32	Home Depot	Poly	interior	06/09/2015
\$30,087.77	\$79.00	P8	Glass, Light bulbs, caulk, etc	interior	06/04/2015
\$30,008.77	\$10.16	Brinton's	Paint Thinner	Exterior	06/08/2015
\$29,998.61	\$12.18	PB	Lock set	Interior	06/05/2015
\$29,986.43	\$40.31	Home Depot	Closet Parts	Interior	06/05/2015
\$29,946.12	\$10.69	PB	Plate	Interior	06/04/2015
\$29,935.43	\$158.25	PB	Glass for Kit Cabinets	Interior	06/01/2015
\$29,777.18	\$147.66	Brinton's	Paint	Exterior	06/01/2015
\$29,629.52	\$3.18	PB	Misc	interior	06/02/2015
\$29,626.34	\$5.65	P8	Goof-off & Mirror Clip Kit	Interior	06/02/2015

Hailing Zhong Johannes Ulirich Project: 152 East 4th St Historic Springfield, FL

ON FILE COMPOSITE EXHIBIT 1 PAGE 79 OF 85

Giory Homes, Inc. CBC059741 7027 Alpine St Jacksonville Florida 32208 Shop: 2018 Walnut St.

Sub Contracts

Date	Ву	Task	Total Project Draw %		Draw Amt	Total
04/21/14	04/21/14 Joe Vanhoy	Complete rewire	\$16,000.00	21.25%	\$3,400.00	\$3,400.00
05/01/14		2 rd Safety draw		6.25%	\$1,000.00	
08/11/14		Basic Draw		12.50%	\$2,000.00	ÌΙ
		Basic Draw		31.00%	\$4,960.00	40
		Under ground		7.00%	\$1,120.00	\$12,480.00
		Basic Draw		12.50%	\$2,000.00	\$14,480.0
		Basic Draw		7.50%	\$1,200.00	\$15,680.00
		Final Draw		2.00%	\$320.00	\$16,000.00
		To Date		100.00%		\$16,000.00
05/01/14	05/01/14 Cannon Plumbing	Complete re-plumbing	\$12,000.00	33.00%	\$3,960.00	\$3,960.00
08/11/14		Top Out		33.00%	\$3,960.00	\$7,920.00
		Trim out		34.00%	\$4,080.00	\$12,000.00
		To Date		100.00%		\$12,000.00
		Floor drain for Mba & Water				
11/13/14	11/13/14 Cannon Plumbing	line for coffee maker	\$490.00	100.00%	\$490.00	\$490.00
		Rework drains MBA dbl sink	\$250.00	100.00%	\$250.00	\$250.00
		Provide 9.5 Rheem tankless	\$1,385.00	100.00%	\$1,385.00	\$1,385.00
05/04/15	05/04/15 Cannon Plumbing	Total all invoices				\$14,125.00
05/01/14	05/01/14 Classic Services	Complete Gas repipe	\$2,675.00	%00.08	\$2,140.00	\$2,140.00
				20.00%	\$535.00	\$2,675.00
				100.00%		\$2,675.00
05/01/14	05/01/14 Jax HVAC	New HVAC	\$10,000.00	34%	\$3,400.00	\$3,400.00

Subs

Hailing Zhong Johannes Ulirich Project: 152 East 4th St Historic Springfield, FL

ON FILE COMPOSITE EXHIBIT 1 PAGE 80 OF 85

Glory Homes, Inc. CBC059741 7027 Alpine St Jacksonville Florida 32208 Shop: 2018 Walnut St.

Subs

			05/08/15 Tim Moore, Brick Mason	05/27/15 JAX Glass		02/19/15 JAX Glass				
			e, Brick Mason	S		S				
Final Total		Pour walkway	Demo & rebuild 4 columns	Total all involces	glass shelves for shower	2 shower doors				
		\$275.00	\$2,275.00			\$2,247.00				
		100%	100%			100%	100%	6%	20%	40%
\$0.00		\$275.00	\$2,275.00			\$2,247.00	\$0.00	\$600.00	\$2,000.00	\$4,000.00
\$0.00 \$48,260.40		\$2,550.00	\$2,275.00	\$2,910.40	\$663.40	69		\$10,000.00	\$9,400.00	

Services

Date By	Task	Unit	Kare	Cost	10281
06/24/14 Shapelis	Dumpster		\$466.00	\$466.00	\$466.00
08/20/14 Shapelis	Dumpster	0.25	\$332.20	\$83.05	\$549.05
10/31/14 Shapells	Dumpster	0.25	\$377.40	\$94.35	\$643.40
11/10/14/Shapells	Dumpster	0.5	\$244.60	\$122.30	\$765.70
03/05/15/Shapells	Dumpster	0.25	\$321.40	\$80.35	\$846.05
03/26/15 Team Recovery	std cage, package cage		\$730.00	\$730.00	\$1,576.05
					\$1,576.05
05/07/15 Home Depot	Boom Lift rental		\$850.00	\$850.00	\$2,426.05
				\$0.00	\$2,426.05

Project: 152 East 4th St Historic Springfield, FL

Hailing Zhong Johannes Ulirich

ON FILE COMPOSITE EXHIBIT 1 PAGE 81 OF 85

Total Project Costs to Date Less Amounts Paid Balance Due Start Up Draw Balances Due	Sub-contractor charges Add-on (Cost plus 15%) Sub-total Services Add-on (Cost plus 15%) Sub Totals Totals	Material Charges Add-on (Cost plus 15%) Totals	Labor Charges Special Labor Credits After Credits Workers Comp Add-on (10%) Company Add-on (15%) Totals	Charges Add-on (Cost plus 0%) Totals	Running Total of Project	Glory Homes, Inc. CBC059741 7027 Alpine St Jacksonville Florida 32208 Shop: 2018 Walnut St.
\$255,472.88 \$1,500.00 \$253,972.88 \$13,500.00 \$240,472.88	\$48,260.40 From Sub Sheet \$7,239.06 \$55,499.46 \$2,426.05 \$363.91 \$2,789.96 \$58,289.42	\$29,597.37 From Material Sheet \$4,439.61 \$34,036.98	\$118,080.70 From Time Sheet -\$1,896.00 \$116,184.70 \$11,618.47 \$17,427.71 \$145,230.88	\$17,915.61 From Admin Sheet \$0.00 \$17,915.61		

Hailing Zhong Johannes Ullrich Project: 152 East 4th St Historic Springfield, FL

Draw Two

\$12,466.81 Paid 07/23/14 Ck# 1288

Invoice

Final Draw	Final adjustments	Balance Due	Draw 12	Balance Due	Draw 11	Balance Due	Draw ten	Balance Due	Draw Nine	Balance Due	Draw Eight	Balance Due	Draw Seven	Balance Due	Draw Six	Balance Due	Draw Six	Balance Due	Draw Five	Balance Due	Draw Four	Balance Due	Draw Three	
\$22,000:00		\$23,199,45	\$15,000.00 Paid 05/21/15 Ck# 1329	\$38,199.45	\$19,000.00 Paid 05/01/15 Ck# 1328	\$57,199.45	\$19,900.00 Paid 03/27/15 Ck # 1320	\$77,099.45	\$21,000.00 Paid 2/24/15 Ck# 1317	\$98,099.45	\$19,700.00 Paid 1/30/15 Ck# 1312	\$117,799.45	\$22,000.00 Paid 1/7/15 Ck# 1310	\$139,799.45	\$18,000.00 Paid 12/03/14 Ck# 1304	\$157,799.45	\$18,000.00 Paid 11/06/14 Ck# 118?	\$175,799.45	\$18,800.00 Paid 10/02/14 Ck# 1171	\$194,599.45	\$18,842.00 Paid 09/15/14 Ck# 1167	\$213,441.45	\$14,564.62 Paid 08/21/14 Ck# 1292	

Page 55

Final Draw

Hailing Zhong Johannes Ullrich

152 East 4th St Historic Springfield, FL Project ON FILE **COMPOSITE EXHIBIT 1** PAGE 83 OF 85

FOREVER FENCE 10710 Skylark Drive Jacksonville, FL 32257 (904) 399-3660

THIS AGREEMENT embodies the entire understanding between Forever Fence (Infinity Fence, LLC, a Florida Corporation) (hereinafter referred to as the "Seller" and represented by its authorized sales agent whose name and signature bind this agreement on the Seller's behalf) and the purchaser, hereinafter referred to as the "Customer". If the Customer is a company, organization, association, subdivision, committee, or any other group, then the person signing this agreement acknowledges their authority to act as agent for such group. The Seller is obligated to communicate only with the Customer, or, in the case of a group, the agent who signed this agreement. If an agent of any group is relieved from his or her duties as agent after the commencement of this Agreement, the replacement agent assumes all of the prior agent is duties in this Agreement. The replacement agent shall not have the right to change any terms of this Agreement except with the specific written consent of the Seller utilizing a written signed and countersigned "change order".

Responsibility for Payment: The Customer is responsible for payment in accordance with the terms of this Agreement. Customer may not base

payment to Seller on the condition of Customer being paid by a third party.		
Name: Hailing + Sohannes ZHong	TOTAL AGREEMENT PRICE	· (8:30)
Address: Lift 15 Fyl	Deposit	s 4.878
City, State, Zip 3206	Balance	s 3252
Email: habiage yahoo, lum	Date Deposit Paid:	6-1-15
Phone (1)	12	_
*Customer understands that materials are not ordered until 100% of require standard orders and four (4) to six (6) weeks for receipt of custom orders. Customer understands that these are estimated times and are under the control for damages if materials are later than anticipated. *Nowhere in this contract limit. There are too many factors that arise in construction; therefore, we do	 The time allowance is from the dolor of the materials manufacturer and not is there a guarantee of an installation 	ate Seller receives the deposit. It Seller. Seller is not responsible
ACCEPTANCE: The prices, specifications, and terms listed above are satisthe work specified herein.	factory and hereby accepted by the Cus	stomer. Seller is authorized to do
Customer: Signature Sciler:	26 ×	age clocke
Date: 6/1/2015 Date:		·
BUYER'S RIGHT TO CANCEL - This is a home solicitation sale, and if you oproviding written notice to the seller in person, by telegram, or by mail. The must be delivered or postmarked before midnight of the third business also may not keep all or part of any cash down parents. In the case of a base of the cash of a business also be a seller to the cash of a business and the cash of a business also be a seller to the cash of a business and the cash of a business also be a seller to the cash of a business and the cash of a business also be a seller to the cash of a business and the cash of a business also be a seller to the cash of a business and the cash of a business and the cash of a business and the cash of a business are the cash of the c	his notice must indicate that you do no after you sign this agreement. If you	ot want the goods or services and cancel this agreement, the seller

has been cancelled.

Seller will also assist you with Architectural Review Boards / Home Owner's Associations. (After deposit, if plans are denied for any reason Seller will refund your deposit in full).

Both the Seller and the Customer acknowledge that no verbal representations have been relied upon in the formation hereof. The Seller shall provide the Customer with the products and services listed in Attachment 1. Any modifications of this Agreement including all attachments must be in the form of a written "change order" and must be signed by both the Seller and the Customer. The Seller and the Customer agree as follows:

Customer Responsibilities: The Customer Must:

- Obtain and submit to Seller all applicable subdivision and Association Covenants and Restrictions, ARC, ARB, permission for all tie ins needed, and generally all permits and approvals necessary for Seller to legally carry out the provisions of this Agreement. If the fence needs to be moved or removed due to ARC guidelines, the cost will be the responsibility of the customer.
- Provide access to water for mixing the concrete.
- Provide a fence line clear of all obstructions including trees, bushes, rocks, roots, concrete, wells, pool lines, vehicles, storage units, etc.
- Provide markings from all applicable public and private utilities including, but not limited to: cable, power, telephone, gas, sprinkler lines, conduit etc. without regard to source. SELLER IS NOT LIABLE FOR ANY DAMAGES TO OR FROM UNMARKED OR IMPROPERLY MARKED UTILITIES.
- Provide properly marked fence lines and property lines. SELLER IS NOT LIABLE FOR UNMARKED OR IMPROPERLY MARKED FENCE LINES AND PROPERTY LINES.

Responsibility for Changes or Delays

If a change order is done, Customer is responsible for all additional material and/or labor charges resulting from such change.



(904) 399-3660 Manager@ForeverFence.US

FENCE PLAN

	在农场上的东西的	NAME OF THE OWNER, OF THE OWNER, OF THE OWNER, OF THE OWNER, OWNER, OWNER, OWNER, OWNER, OWNER, OWNER, OWNER,							
Name	Hailing ZHong	Date			Other				
Community		♥ Aluminum	□ Vinyl (说1· 19/1	e. 1 /1 -				
Phone	1 210-1555 21	Height 🗆 3'	4' 0.4 1/2' 0.5'						
E-mail	3.67		White □ Tan □ 8	ronze 🗆 Other					
Address	152 F 1/2 55.32200	Style:							
City, State ZIP Code	137 8	. EXHOA/ARB	☐ Tear Do	wn / Removal					
Layout:			Legend:		0/4k-1335				
	See planing								
	Diaring								
120									
			li .	·					
F 71 2									
3									
. ·									
	(*)			te.					
- /									
Notes:			1						
of the same of the	C/3.00								
eren .	Carl Street	3578	3. T.						
Total Feet		Total Investme	ent	8130					
# of Gates		Deposit		4878					
·		मार्गालका स्वरं	terra est	The state					
 Lifetime Warrant 	y on MATERIALS	◆ Ufetime Warrant	ty on INSTALLATION						
	and Mixed Concrete	 Expert Installation 	Expert Installation Techniques						
Owner involved i		Dedicated Custo	mer Care Departmen	nt					
The state of the state of	A STATE OF THE PARTY OF THE PAR				COLUMN A				
Customer Signature		Forever Fence Signature	2						
Name		Name	Kur	(nock or					
Date		Date	5-20	(nocker					
1.									

FOREVER FENCE - Fence Plan - Attachment 1